RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

2961 E. COLORADO ST., PASADENA, CALIF.

No. 11899

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080063-4

RECEIVED FROM PLANT #9

DATE REC'D. 4-15-57

P.O. NO.

VENDOR PACKING SLIP NO.

CHARGE TO	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	OR	ACCT. OR W.O. NO. / S.O. NO.
	322		036	0	10					

QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION	QUANTITY ACCEPTED	QUANTITY REJECTED	REMARKS
120	731461 Gasket Timer Stem	120	—	New Lot
	IPS #5553			

RECEIVED BY [signature] HMC-1069

INSPECTED BY [signature] DATE 4-15-57

REJECTS RETURNED ON SHIP. MEMO NO.

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

2961 E. COLORADO ST., PASADENA, CALIF.

No. 11905

RECEIVED FROM PLANT #9

DATE REC'D. 4-15-57

P.O. NO.

VENDOR PACKING SLIP NO.

CHARGE TO	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	OR	ACCT. OR W.O. NO. / S.O. NO.
	322		296	0	3					

QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION	QUANTITY ACCEPTED	QUANTITY REJECTED	REMARKS
50	737839 Connector Miniature	50	✓	New Lot
	IPS #5395			

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080063-4

RECEIVED BY [signature] HMC-1069

INSPECTED BY [signature] DATE 4-15-57

REJECTS RETURNED ON SHIP. MEMO NO.